DMS 1908 Gr. 3

U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing, Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

		SECT	ION I					
MAGNAFLUX CORPORATION EMERGENCY TELEPHONE NO. (312) 867-8000								
ADORESS Number, Street, City, State, and ZIP C 7300 West Lawrence Avenue, C	hicas	zo, Illino	is 60656					
CHEMICAL NAME AND SYNONYMS		• , •	TRADE NAME AND SYNONYMS ZL-60B Zyglo Penetrant					
CHEMICAL FAMILY			FORMULA					
SECTION	V 11 -	HAZAR	DOUS INGREDIENTS					
PAINTS, PRESERVATIVES, & SOLVENTS	×	TLV (Units)	ALLOYS AND METALLIC COATINGS	*	TLV (Units)			
PIGMENTS			BASE METAL					
CATALYST		-	ALLOYS					
VEHICLE			METALLIC COATINGS					
SOLVENTS	1		FILLER METAL PLUS COATING OR CORE FLUX	1	 			
ADDITIVES	1		OTHERS					
OTHERS 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		/	and the property of the second					
HAZARDOUS MIXTURE	S OF	OTHER LIC	UIDS, SOLIDS, OR GASES	*	TLV (Units)			
Kerosene Caracteria (Caracteria Caracteria C								
				30	100 mgm			
				+-				
				-				
								
SE	CTIO	N III - P	HYSICAL DATA					
BOILING POINT (F.)	40	000F IBP	SPECIFIC GRAVITY (H20=1)		0.88			
VAPOR PRESSURE (mm Hg.)	12		PERCENT VOLATUE		10%			
VAPOR DENSITY (AIR=1)		1 1000F	EVAPORATION RATE		Von81			
SOLUBILITY IN WATER			le	100				
APPEARANCE AND ODOR Green oily liquid, oily smell.								
Green only				4				
	FIR	E AND E	XPLOSION HAZARD DATA	3				
FLASH POINT (Method used) 2000F PM (Close	d Cup	FLAMMABLE LIMITS Lei	157	Uei			
EXTINGUISHING MEDIA CO2, Foam				10.	5 ×			
			·		Carrie			
SPECIAL FIRE FIGHTING PROCEDURES	Non							
SPECIAL FIRE FIGHTING PROCEDURES	Non	16						
SPECIAL FIRE FIGHTING PROCEDURES UNUSUAL FIRE AND EXPLOSION HAZARDS	Nor Nor							

PAGE (1)

(Continued on reverse side)

Form OSHA-20

					•				
		ECTION	V - HEAL	TH HAZAR	ID DATA				
THRESHOLD LIMIT VALUE 500 ppm									
EFFECTS OF OVERE	XPOSURE		<u>տ իրտ</u>	· · · · · · · · · · · · · · · · · · ·					
Dizziness, d	rausiness, naus IRST AID PROCEDU	ea. Irri IR ES	tating to s	kin. Moder	ately irritating to eyes.				
Remove to	fresh air Wash	off als:							
with water.	HEST AIL WAS	LOU SKI	n promptly	with soap	and water. If in eyes, rinse copiously				
The state of the s									
SECTION VI - REACTIVITY DATA									
STABILITY .	UNSTABLE .		CONDITION	S TO AVOID					
* . 	STABLE	X'							
May dissolve or soften rubber, plastics and organic coatings									
HAZARDOUS DECO	MPOSITION PRODU		None		The state of the s				
HAZARDOUS	MAY OCCU	MAY OCCUR		CONDITIONS TO AVOID					
POLYMERIZATION	WILL NOT	WILL NOT OCCUR		x					
		,	لبسبي جاسب						
SECTION VII - SPILL OR LEAK PROCEDURES									
STEPS TO BE TAKE	IN CASE MATERI	AL IS REL	EASED OR SE	PILLED					
Soak up with	absorbent con	pounds	and sweep	up. Can be	e flushed away with water spray.				
No smoking.			······································						
WASTE DISPOSAL M	ETHOO								
Material is c	ombustable, ca	n be bu	rned, or ei	se treat as	oily waste. Not a hazardous waste.				
	•			oc acat as	ony waste. Not a hazardous waste.				
	SECTION	VIII - S	PECIAL PR	ROTECTION	INFORMATION				
RESPIRATORY PROT	ECTION (Specify ty	pe) No	ne						
VENTILATION	LOCAL EXHAUST		ray Booth i	f sprayed	SPECIAL				
	MECHANICAL (Ger				OTHER				
PROTECTIVE GLOVE Neoprene glo	s ves if exposure	is unav	voidable	EYE PROTECT	rion None				
OTHER PROTECTIVE	EQUIPMENT	No	·		None				
				IAL PRECA	UTIONS				
PRECAUTIONS TO BE	TAKEN IN HAND	LING AND	STORING						
Store in dry p	olace, away fro	m heat	sources.	1					
OTHER PRECAUTION	15			o irritation	. Wipe off promptly.				
	rated clothing.	_			The Man of the Control of the Contro				

PAGE (2)

Form OSHA-20 Rev. May 72